



tending contractors must undertake a site inspection, any discrepancies discovered shall be reported to the client and to IPL immediately for assessment, and they must be clearly and concisely qualified within tender return submissions.

- | | |
|-------------------------------------|-----------------------|
| <input type="checkbox"/> | AS BUILT DRAWING |
| <input type="checkbox"/> | LICENSING |
| <input type="checkbox"/> | REVISION REF _____ |
| <input type="checkbox"/> | CONSTRUCTION ISSUE |
| <input type="checkbox"/> | TENDER ISSUE |
| <input type="checkbox"/> | BUILDING REGULATIONS |
| <input checked="" type="checkbox"/> | LPA SUBMISSION |
| <input type="checkbox"/> | LPA PRE-APP |
| <input type="checkbox"/> | FOR APPROVAL _____ |
| <input type="checkbox"/> | FEASIBILITY NR _____ |
| <input type="checkbox"/> | DRAFT FOR DISCUSSION |
| <input type="checkbox"/> | SURVEY |

Rev	Date	Description
01	21/07/21	For Approval
02	29/07/21	Update for final approval
03	17/08/21	Playground update for Approval
04	26/08/21	Update to LPA submission
05	13/09/21	Update for LPA submission

Retail Cafe	FOH 1.25 sqm
-------------	--------------

	BOH	38 sqm
<u>Exterior Canopy</u>		157 sqm

Butlin's

Project:

CAFE & PLAYGROUND

ient:

BUTLINS RESORT
ROMAN BANK
SKEGNESS
PE25 1NJ



Drawn: JD Approved: JULY 2021

Scale: 1 : 100 @ A1 PRINT SIZE

Sheet Description:

PROPOSED OPERATIONAL
LAYOUT - 2 of 2

Sheet Number:

IPL 21 363/13 103

je:

5-LPA